DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS 11412-101 REV. F OR LATER APPROVED REVISIONS AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA412-101 REV. E OR LATER APPROVED REVISIONS

REF. TCCA STC: SH21-30 REF. FAA STC: SR02289LA REF. EASA STC: 10061316 REF. JCAB STC-520-TYO

1.0 PURPOSE

It has come to Dart's attention that on some aircraft, the Breakaway Tip of the Lower Cutter Assembly may interfere with existing mission critical equipment installed on the aircraft. The purpose of this Dart Service Instruction (DSI) is to support the removal of the Lower Cutter Assembly Breakaway Tip and eliminate the interference.

2.0 REMOVAL OF BREAKAWAY TIP

- 2.1 With reference to Figure 1, It is acceptable to remove the P/N 647.3913 or 647.3914 Breakaway Tip by drilling out and removing the P/N 601.3074 rivets that secure the Breakaway Tip to the 647.3901 or 647.3902 Deflector of the Lower Cable Cutter Assembly. Remove qty(2) Rivet P/N 601.3074 on Deflector P/N 647.3901 or gty(3) Rivet P/N 601.3074 on Deflector P/N 601.3092.
- 2.2 Remove rivet shavings and clean off sealant.
- 2.3 Inspect parts and finish on parts per Section 5.3.2 of ICA412-101.
- 2.4 Make an entry into the aircraft logbook to indicate removal of the Lower Cutter Breakaway Tip per DSI 9903 and adjust Aircraft Weight and Balance with the Weight and Balance information provided in Section 4.0 of this DSI.

3.0 REINSTALLATION OF BREAKAWAY TIP

- 3.1 If no equipment interferes with the installation of the Breakaway Tip, it is acceptable to reinstall per Section 5.3.3 of the ICA412-101 by replacing Rivet P/N 601.3074 with MS27039-1 Screws, NAS1149D0332J Washers, and MS21042L3 Nuts per Figure 2. Apply RTV (Loctite 598 or equivalent) to all faying surfaces. Torque screws 20-25 in-lbs (2.2-2.8 N.m).
- 3.2 Make an entry into the aircraft logbook to indicate that the Lower Cutter Breakaway Tip has been installed per DSI 9903 and adjust Aircraft Weight and Balance with the Weight and Balance information provided in Section 4.0 of this DSI.

NEW ISSUE DEASON ECD 484

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01 APPROVED

D. SHEPHERD (DE # 02)

23.02.16 DATE: CERT. NO .: SH21-30 ISSUE NO .:

APPROVED	A	NEW ISSUE REASON ECR 481			SAU	23.02.16	
	REV.			DESCRIPTION	BY	DATE	
	DESIGN		SAD	DART AFPOSPACE			
	DRAWN		SAD	DART AEROSPACE HAWKESBURY, ONTARIO, CANADA			
	CHECKED		MB	DRAWING NO.		REV. A	
	MFG. APPR.		N/A	DSI 9903	S	SHEET 1 OF 2	
	APPROVED		SAD	TITLE		SCALE	
	DE APPR.		DS	CCK FASTENER REPLACE	ACEMENT NTS		
	DATE 23.02.16			COPYRIGHT © 2023 BY DART AEROSPACE. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPORSE OR OPERS OR COMMUNICATED TO ANY OTHER PERSON WITHOUT			

NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AFROSPACE




FIGURE 1: REMOVAL OF BREAKAWAY TIP




FIGURE 2: RE-INSTALLATION OF BREAKAWAY TIP

4.0 WEIGHT AND BALANCE

P/N	Weight	Long Arm	Long Moment
647.3913	0.40 lbs	27.7 ln	11.1 lb-in
Breakaway Tip	0.18 kg	0.70 m	0.13 Kg-m
647.3914	0.83 lbs	26.8 In	22.2 lb-in
Breakaway Tip	0.38 kg	0.68 m	0.26 kg-m

0	7
Ĺ	П
2	>
è	ř
Č	ŕ
_	Į

DESIGN	SAD
DRAWN	SAD
CHECKED	MB
MFG. APPR.	N/A
APPROVED	SAD
DE APPR.	DS J
DATE 23.0	2.16

DART AEROSPACE HAWKESBURY, ONTARIO, CANADA DRAWING NO. DSI 9903 SHEET 2 OF 2

TITLE

SCALE CCK FASTENER REPLACEMENT

COPYRIGHT @ 2023 BY DART AEROSPACE. THIS DOCUMENT IS PRIVATE AND COMPIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DATA LARGOSPACE.

REV. A